

404.371.2155 (o) 404.371.4556 (f) DeKalbCountyGa.gov 178 Sams St Decatur, GA 30030

Chief Executive Officer Michael Thurmond

DEPARTMENT OF PLANNING & SUSTAINABILITY

Interim Director Cedric Hudson

Land Development Environmental Inspection Report				
Inspector Name: A. McDyess/E. Emmett/D. Pearson	Date: 4/4/2023			
Owner/Tenant/Contractor: Alan Williams	Phone: 770-354-3392			
Address of Subject Property: 561 Key Rd / 1350 Constitution	District/Zone: 15 081 08 001			
Permit No.: 1245564	NPDES Tracking No. N/A			
 <u>Site Visit Purpose:</u> Follow-up site inspection after the Zoom appointment	Compliance/Violation Determination: -BMPs compliance obtained -Silt Fence in the GA Power Easement Area that the protesters damaged/destroyed has been corrected No sediment escape or environmental impacts observedRepairs to all the silt fence and tree protection has been made, the site is in compliance and is environmentally up to DeKalb County Ordinance.			
Notice of violations Issued? No, construction violations were observed.	Stop Work Order issued? Yes No			
Follow up action: TBD	Re-inspection date: TBD			
Violations code reference: None				
Referred to another department/division: No				

General Observations

deneral observations			
Storm water violation	NO	Rain Fall Incident?	NO
Construction site violation	NO	Discharge event?	NO
BMP's Install Properly?	YES	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	NO
During Storm event	N/A	Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?	N/A
Post Storm Event?	YES	Are all slopes and disturbed areas not actively being worked properly stabilized?	N/A
Stream buffer violations?	NO	Are discharge points and receiving waters free of sediment deposits?	N/A

Report Certification

Position/Title:	Name:	Signature	Date
Site Inspector	Deidra Pearson	Durch	4/5/2023

Inspection Photos:

Re: 1350 Constitution/561 Key

COMPLIANCE STATUS:





Previously Destroyed Perimeter Silt Fence at Power Easement Area





ENTRANCE on KEY ROAD (33.69685841N 84.33796873W)





Silt fence repaired where fallen tree damage took place; Hay bales and an extra row of silt fence was added for additional stabilization